


Condensor Components



Service Parts
Condensor Fan Blades
301103, zzzzzz, 410002, 410015, 410019, zzzzzz



301103 - Fan Guard,

Note: Replaces
301355



410002 - Fan 5- Blade, 10", 30 Deg Pitch



410015 - Fan 4-Blade, 10", 30 Deg Pitch, T/A 3 Fan
Rooftop, Hispacold Retrofit Kit



410019 - Fan 4-Blade, 18", Used on TA2

Note: Available only while supplies last

